


SL.NO	DATE	COMPLAINT	NAME OF THE ATTENDING PERSON	WORK DONE	SIGNATURE	REMARKS
01.	06/12/2019	Room no: 30: 2 benches legs are shaking.	Carpenter Selvan	✓	Selvan	Work Completed
02.	06/12/2019	Room no: 28: 01 bench is Repair.	"	✓	Selvan	
03.	06/12/2019	Room no: 27: 01 bench without desk.	"	✓	Pee	
04.	20/12/2019	Room no: 16: 02 benches are damaged	"	✓	Pee	
05.	20/12/2019	Room no: 19: 02 benches ^{legs} are shaking.	"	✓	Pee	
06.	20/12/2019	Room no: 18: 03 benches are screw lose.	"	✓	Pee	
07.	20/12/2019	Room no: 22: 01 bench is damaged.	Sankar	✓	Sankar	
08.	20/5/2022	Lockers to be placed in all dept.	4/16/22] Mr. Annamalai Mr. Nagarajan	lockers fixed in all department.	Annamalai Nagarajan	
09.	10/6/22	Repack all room (windows frame bolts)	ES ELVAN	no fixer list fix	ES	L
10.	11/7/22	Tube lights to be replaced.				L
11.	20/7/22	Fan regulator are not work		Regulator fix		L
12.	05/8/22	1st floor Room No. 59, All drop. Repaired Store Room All drop Damaged.	Sankar	All drop Repaired	Sankar	Work Completed
13.	31/10/22	Grand floor Main Door (Guest Room) And Bath Room door Repaired. Sick Room & Bath Room Vandal Repaired.	Sankar	Door's Repaired	Sankar	Work Completed

AQAR II

NAAC COORDINATOR
 Sri Devaraj Urs College of Nursing
 Tamaka, Kolar-563103


Principal
 Sri Devaraj Urs College of Nursing
 Tamaka, Kolar-563103

Sl. No	Date	Complaint	Incharge	Remarks
31.	18/11/21	Tube lights not working I floor Corridor (03) non-teaching (01)	Incharge electrician signature Shree	working
32	27/11/21	Fan regulators are not working (ped. reg. Department)	Shree	working
33.	25/1/22	class room mike to fixed I B-sc (n) - II B-sc (n) III B-sc (n) IV B-sc (n).	Mr. Srinivas Mr. Nagaraj	working
34.	26/1/22	fixed mike in I, II, IV B-sc except II B-sc (n) <small>no amplifier no speaker.</small>	Mr. Nagaraj	working
35.	26/5/22.	No power supply. (02hr) (Cable wire damaged - generator room) re	Mr. Nagaraj	After 2 hrs power supply got rest (checked cable wire)
36	31/5/22.	I floor 3 tubes not working 2 Corridor 1 II B-sc class room II floor 2 tubes not working IV B-sc class room switch board not working	-	100
37	4/7/22.	Hostel - IV floor - 93 tube light replaced II floor - tube replaced. Room no - (Shock) - checked and corrected.	Mr.	work complete

Sl. No	Date	Complaint	Incharge	Remarks
9/8/22	9/8/22	plug point - repaired	Shree	working
11/8/22	11/8/22	Verified Mike - Working II B-sc (no mike) with I B-sc (n) Working III B-sc (n) / no cable. IV B-sc (n) / no cable	Shree	Working Working working
		fixed mike at all 3-cc class room		
24/9/22	24/9/22	R-1, 19, 11, 12, 14, 15, 14, 16 plug, Swiker board Regulator, light fan, regulator (All repaired)	Shree	Requested 24/9/22
10/10/22	10/10/22	Room - 23, 27, 31, 33, 37 39, 28, 46, 91, 10, 95, 43, 34, 4 bus tube light, Regulator, plug & switch, Scaling fan, & Capacitor		

20/12/22

Page No. /801
Date / /
Principal
Sri Devaraj Urs College of Nursing
Tamaka, Kolar-563103
Scanned with OKEN Scanner